

Town Shores of Gulfport No. 212 Inc., A Condominium

LOCATION:

5980 SHORE BLVD SOUTH GULFPORT, FLORIDA 33707



IP RISK SERVICES, INC. 9700 TIFFANY OAKS LANE, SUITE 200 TAMPA, FL 33612-7510

Email: IPRiskServices@aol.com

PROFESSIONALLY LICENSED

THIS REPORT FORMAT IS COPYRIGHTED BY IP RISK SERVICES, INC.





INSURANCE INSPECTION REPORT



PREPARED FOR THE FOLLOWING INSURANCE RISK: TOWN SHORES OF GULFPORT NO. 212 INC., A CONDOMINIUM

LOCATION:

GULFPORT, FLORIDA

THIS INSURANCE INSPECTION REPORT WAS CREATED TO ASSIST INSURANCE UNDERWRITERS IN CORRECT IDENTIFICATION OF CONSTRUCTION COMPONENTS FOR INSURANCE RATING PURPOSES. THE REPORT IDENTIFIES THE COMPONENTS CONSTRUCTION OF THE RISK IN ORDER TO MEET CERTAIN REQUIREMENTS OF AN INSURANCE POLICY. THE REPORT ASSISTS IN AVOIDING CO-INSURANCE PENALTIES OF THE INSURANCE POLICIES. THIS REPORT IS IN ADHERENCE WITH STATE INSURANCE STATUTES AND FEDERAL FLOOD INSURANCE REQUIREMENTS.

THE REPORT IDENTIFIES AREAS SUCH AS THE ROOF, EXTERIOR WALLS, FOUNDATIONS, FRAME, FLOORS, CONVEYING SYSTEMS, KITCHENS, HVAC, ELECTRICAL, PLUMBING, FIRE SPRINKLERS AND OTHER CONSTRUCTIONCOMPONENTS VITAL TO THE INSURANCE RATING.

THIS REPORT IS NOT A REAL ESTATE APPRAISAL. THIS REPORT IS AN INSURANCE REPORT ONLY. THE CONCLUSIONS IN THIS REPORT UTILIZE ACCEPTABLE INSURANCE METHODS ONLY.

AN INSURANCE INSPECTION HAS BEEN MADE OF THE RISKS IN THIS REPORT.

UPDATE- October 18, 2021

Original Inspection- Craig Markowich

P/P Consultants:

CRAIG MARKOWICH
KEN TAZZA
KAREN G. LEWANICK
JONATHAN FIELDS

CRAIG MARKOWICH KEN TAZZA KAREN G. LEWANICK JONATHAN FIELDS

I P Risk Services, Inc. 3559 Fairway Forest Drive, Suite 3559 Palm Harbor, Florida 34685

Email: IPRiskServices@aol.com
Core Logic Estimating System



***** ELOPIDA CONDOMINIUM LAWS DEOVIDE AN

****** FLORIDA CONDOMINIUM LAWS PROVIDE AN EXCLUSION OPTION ON CERTAIN ITEMS AS DESCRIBED BELOW:

A hazard insurance policy issued to an association must provide primary coverage for all condominium property as originally installed or replacements of like kind and quality in accordance with original plans and specifications, and all alterations or additions made to condominium or association property but **excluding** all personal property within a unit or limited common element; floor; wall and ceiling coverings; electrical fixtures; appliances; water heaters; water filters; built-in cabinets and countertops; and window treatments; including curtains; drapes; blinds; hardware; and similar window treatment components or replacements of any of the foregoing which are located within the boundaries of a unit and serve only one unit.

The foregoing is intended to establish the property or casualty insuring responsibilities of the association and those of the individual unit owner and do not serve to broaden or extend the perils of coverage afforded by any insurance contract provided to the individual unit owner.





INSURANCE RESPONSIBILITIES AS GOVERNED BY **FLORIDA STATUTE 718**

	Condominium Association Responsibility	Individual Unit Owner Responsibility
1. ROOF AND ROOF COVER Structural Framing and Roo	YES of Cover	NO
2. EXTERIOR WALLS Paint, stucco, insulation, st Concrete Block, Brick, etc.	YES ^t uds,	NO
3. UNIT INTERIOR WALLS Party Walls, Unfinished dry insulation, metal and wood	-	NO
4a. COMMON AREA Interior W	<i></i> <i>I</i> alls	
Studs, Block and Drywall 4b. COMMON AREA Floor, Wa	<i>YES</i> III.	NO
and Ceiling Finishes	YES	NO
5. UNIT INTERIOR Floor, Walk	 l & Ceiling Finishes	
Paint, Carpet, tile, etc.	NO	YES
6. UNIT AND COMMON AREA		
-Structural Floors	YES	NO
-Structural Ceilings	YES	NO
-Structural Walls	YES	NO
7. Common Area Air Condition	 ners <i>YES</i>	NO
8. Common Area Electrical	YES	NO
9. INTERIOR UNIT COMPONE	 NTS	
- Appliances	NO	YES
- Electrical Fixtures	NO	YES
- Air Conditioners	YES	NO
- Water Heaters	NO	YES
- Cabinets	NO	YES

^{****}The above information is intended to assist in determining the general responsibilities for both parties. IP makes no warranties as to individual Association legal interpretations.

IP







INSURANCE EXCLUSIONS

CERTAIN ITEMS ARE EITHER NOT INSURED, OR ARE SPECIFICALLY EXCLUDED FROM COVERAGE, DEPENDING ON THE PARTICULAR TERMS OF AN INSURANCE POLICY.

FOUNDATIONS <u>BELOW</u> GROUND AND PIPING <u>BELOW</u> GROUND ARE NORMALLY EXCLUDED FOR INSURANCE PURPOSES.

THE EXCLUSION FIGURES IN THE HAZARD

RECAPITULATION PAGE ARE THE CALCULATED

PERCENTAGES OF FOUNDATIONS AND PIPING

BELOW GROUND.

POWERED BY CORE LOGIC AND UNDERWRITTEN BY LLOYD'S OF LONDON



MANDATORY FEDERAL FLOOD INSURANCE POLICY REQUIREMENTS

FEDERAL FLOOD REQUIREMENTS INCLUDE THE THE FOLLOWING ITEMS FOR RESIDENTIAL CONDOMINIUM UNITS:

- All Foundations including below ground
- All Piping including below ground
- All Excavation and site preparation work
- All Structural floors, walls, ceilings and roof
- All Electrical Wiring and Plumbing
- All Interior Floor Wall & Ceiling Finishes
- All appliances, air conditioners, water heaters Electrical fixtures and built-in cabinets.

ALL CONDOMINIUMS ARE MANDATED TO ADHERE TO THE FEDERAL FLOOD REQUIREMENT VALUATIONS.

IP REP	PORTS REFLEC	T THESE GUIDELINES	5.

INSURANCE RESPONSIBILITIES AS GOVERNED BY NATIONAL FLOOD INSURANCE PROGRAM-FEMA

	Condominium Association Responsibility	Individual Unit Owner Responsibility
1. ROOF AND ROOF COVER Structural Framing and Roof	YES Cover	NO
2. EXTERIOR WALLS Paint, stucco, insulation, stu Concrete Block, Brick, etc.	YES ds,	NO
3. UNIT INTERIOR WALLS Party Walls, Unfinished drywinsulation, metal and wood st	•	NO
4a. COMMON AREA Interior Wa Studs, Block and Drywall 4b. COMMON AREA Floor, Wall	YES	NO
and Ceiling Finishes	, YES	NO
5. UNIT INTERIOR <i>Floor, Wall Paint, Carpet, tile, etc.</i>	& Ceiling Finishe YES	s NO
6. UNIT AND COMMON AREA		
-Structural Floors	YES	NO
-Structural Ceilings	YES	NO
-Structural Walls	YES	NO
7. Common Area Air Conditions	ers <i>YES</i>	NO
8. Common Area Electrical	YES	<i>NO</i>
9. INTERIOR UNIT COMPONEN	TS	
- Appliances	YES	NO
 Electrical Fixtures 	YES	NO
- Air Conditioners	YES	NO
- Water Heaters	YES	NO
- Cabinets	YES	NO

^{****}The above information is intended to assist in determining the general responsibilities for both parties. IP makes no warranties as to individual Association legal interpretations.



Town Shores of Gulfport #212
Diplomat Building
Hazard Valuation

10/18/2021

VALUATION

Value Basis:

Valuation Number: ESTIMATE-0001360

Effective Date: 10/18/2021

Reconstruction Expiration Date: 10/18/2022

Estimate Expiration Date: 10/25/2022

Cost as of: 06/2021

BUSINESS

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

LOCATION 1 - Town Shores of Gulfport Condominium

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 0000000 - Residential Building

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium, w/o Interior Story Height: 9 ft.

Finishes

Construction Type: 100% Reinforced Concrete Frame (ISO Number of Stories: 10

6)

Gross Floor Area: 191,620 sq.ft. Irregular None

Adjustment:

Construction Quality: 2.0 - 2.0 - Average

Year Built:

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Town Shores of Gulfport #212
Diplomat Building
Hazard Valuation

Policy Number: ESTIMATE-0001360 10/18/2021

% is included			
	Recons	struction	Exclusion
			\$5,188
	;	\$132,563	\$74,362
ns, Slab On Ground			
	\$9	9,340,080	
l, Structural Floor, Roof			
	\$5	5,126,645	
S			
	\$4	1,017,412	\$514,221
umbing, Electrical, Elevators			
	\$1	,990,156	
	\$20,606,856		\$593,77
TOTAL RC BUILDING 0000000 Residential Building		20,606,856	\$593,771
Reconstruction	Sq.Ft.	\$/Sq.F	t.
\$20,606,856	191,620	\$10	8
Reconstruction	Sq.Ft.	\$/Sq.F	t.
\$20,606,856	191,620	\$10	8
	ns, Slab On Ground I, Structural Floor, Roof s umbing, Electrical, Elevators ntial Building Reconstruction \$20,606,856 Reconstruction	Recons as, Slab On Ground \$5 I, Structural Floor, Roof \$5 s umbing, Electrical, Elevators \$1 \$2 Intial Building \$2 Reconstruction \$4 \$20,606,856 \$191,620 Reconstruction \$9 \$4	\$132,563 as, Slab On Ground \$9,340,080 by, Structural Floor, Roof \$5,126,645 s \$4,017,412 umbing, Electrical, Elevators \$1,990,156 \$20,606,856 ential Building \$20,606,856 Reconstruction \$q.Ft. \$/\$q.F

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Town Shores of Gulfport #212 Diplomat Building Hazard Valuation SUMMARY REPORT

Policy Number: ESTIMATE-0001360 10/18/2021

VALUATION

Valuation Number:ESTIMATE-0001360Effective Date:10/18/2021Value Basis:ReconstructionExpiration Date:10/18/2022Estimate Expiration Date:10/25/2022

Cost as of: 06/2021

BUSINESS

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

LOCATION 1 - Town Shores of Gulfport Condominium

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

BUILDING 000	0000: SU	PERSTRUCTURE	Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section 1	100%	Condominium, w/o Interior Finishes	\$20,606,856	191,620	\$108	
Section To	tals		Reconstruction	Sq.Ft.	\$/Sq.Ft.	
Section 1	100%	Condominium, w/o Interior Finishes	\$20,606,856	191,620	\$108	
BUILDING TO	TAL, Buil	ding 0000000	\$20,606,856	191,620	\$108	
BUILDING INS	URANCE	SUMMARY				
Total Insured A	mount		\$0			
Percent of Insu	rance to \	/alue	0%			
100% Co-insur	ance Req	uirement	\$20,606,856			\$20,606,856
-100% Variance	е		(\$20,606,856)			
			Reconstruction	Sq.Ft.	\$/Sq.Ft.	
OCATION TOTA	L, Locati	on 1	\$20,606,856	191,620	\$108	
			Reconstruction	Sq.Ft.	\$/Sq.Ft.	
ALUATION GRA	ND TOT	AL	\$20,606,856	191,620	\$108	
			End of Donort			

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



10/18/2021

Town Shores of Gulfport #212
Diplomat Building
Flood Valuation

VALUATION

Value Basis:

Valuation Number: ESTIMATE-0001360

Effective Date: 10/18/2021

Reconstruction Expiration Date: 10/18/2022

Estimate Expiration Date: 10/25/2022

Cost as of: 06/2021

BUSINESS

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

LOCATION 1 - Town Shores of Gulfport Condominium

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

Location Adjustments

Climatic Region: 3 - Warm

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 0000000 - Residential Building

Section 1

SUPERSTRUCTURE

Occupancy: 100% Condominium Story Height: 9 ft.

Construction Type: 100% Reinforced Concrete Frame (ISO Number of Stories: 10

6)

Gross Floor Area: 191,620 sq.ft. Irregular None

Adjustment:

Construction Quality: 2.0 - 2.0 - Average

Year Built:

Adjustments

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

Overhead and Profit: 20% is included

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Town Shores of Gulfport #212
Diplomat Building
Flood Valuation

Policy Number: ESTIMATE-0001360 10/18/2021

SUMMARY OF COSTS		Reconstruction Exclusion			
SUPERSTRUCTURE					
Site Preparation		\$5,054			
Foundations		\$201,573			
Foundation Wall, Interior Foundations, Sla	ab On Ground				
Exterior		\$9,098,526			
Framing, Exterior Wall, Exterior Wall, Stru	uctural Floor, Roof				
Interior		\$6,702,129			
Floor Finish, Ceiling Finish, Partitions					
Mechanicals		\$6	,263,400		
Heating, Cooling, Fire Protection, Plumbin	ng, Electrical, Elevators				
Built-ins		\$2	,243,481		
TOTAL RC Section 1		\$2	4,514,165		
TOTAL RC BUILDING 0000000 Residential Building		\$2	4,514,165		
	Reconstruction	Sq.Ft.	\$/Sq.Ft.		
LOCATION TOTAL, Location 1	\$24,514,165	191,620	\$128		
	Reconstruction	Sq.Ft.	\$/Sq.Ft.		
VALUATION GRAND TOTAL	\$24,514,165	191,620	\$128		

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.



Town Shores of Gulfport #212 Diplomat Building Flood Valuation SUMMARY REPORT

Policy Number: ESTIMATE-0001360 10/18/2021

VALUATION

Valuation Number:ESTIMATE-0001360Effective Date:10/18/2021Value Basis:ReconstructionExpiration Date:10/18/2022

Estimate Expiration Date: 10/25/2022 Cost as of: 06/2021

BUSINESS

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

LOCATION 1 - Town Shores of Gulfport Condominium

Town Shores of Gulfport #212 Condominium

5980 Shore Blvd S

Gulfport, FL 33707-5942 USA

Reconstruction	Sq.Ft.	\$/Sq.Ft.	
\$24,514,165	191,620	\$128	
Reconstruction	Sq.Ft.	\$/Sq.Ft.	
\$24,514,165	191,620	\$128	
\$24,514,165	191,620	\$128	
\$0			
0%			
\$24,514,165			\$24,514,165
(\$24,514,165)			
Reconstruction	Sq.Ft.	\$/Sq.Ft.	
\$24,514,165	191,620	\$128	
Reconstruction	Sq.Ft.	\$/Sq.Ft.	
\$24,514,165	191,620	\$128	
	\$24,514,165 Reconstruction \$24,514,165 \$24,514,165 \$0 0% \$24,514,165 (\$24,514,165) Reconstruction \$24,514,165 Reconstruction	\$24,514,165 191,620 Reconstruction Sq.Ft. \$24,514,165 191,620 \$24,514,165 191,620 \$0 0% \$24,514,165 (\$24,514,165) Reconstruction Sq.Ft. \$24,514,165 191,620 Reconstruction Sq.Ft.	\$24,514,165

End of Report

CoreLogic costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

The commercial contents values CoreLogic publishes in this report are estimates only and should not be considered the actual value of commercial contents insurance coverage that should be underwritten for the insured.